

Sample and Calibration Gas Input Pressure Range

Unless stated otherwise in the product documentation, ensure that the pressure of the calibration and sample line is regulated at 3 to 30 PSIG (15 PSIG recommended).