



LP-Gas Equipment

Emerson Process Management  
Regulator Technologies, Inc.

3200 Emerson Way  
McKinney, TX 75070 USA

**August 17, 2015**

## **IMPORTANT SAFETY RECALL**

### **VOLUNTARY SAFETY RECALL CAMPAIGN #15E064**

Dear Owner of Fisher Pressure Relief Valve Model H732A, H832A, H733 or H833 with relief pressure settings up to 200 psig:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

Emerson Process Management Regulator Technologies, Inc. has decided that a defect which relates to motor vehicle safety exists in some 3" Fisher models H732A, H832A, H733 and H833 pressure relief valves. Affected relief valves are limited to those with relief setpoints up to 200 psig. If the cargo transport in which the relief valve is installed is involved in an accident or other emergency scenario and directly exposed to fire, the flow rate from the relief valve may be restricted to less than the rated flow of the relief valve. The restricted relief valve flow may increase the likelihood of a transport tank boiling liquid expanding vapor explosion (BLEVE) if exposed to a fire and may result in personal injury.

In late July 2015, Emerson Process Management Regulator Technologies, Inc. received test results and information indicating that the H732A, H832A, H733 and H833 relief valves with relief pressure settings up to 200 psig had been installed in cargo transports and may have relief valve flow capacity less than rated flow capacity. Emerson Process Management Regulator Technologies, Inc. has decided based on this recent information to replace all of the subject relief valves with relief setpoints up to 200 psig as a precautionary measure.

**This voluntary recall affects only 3" Fisher models H732A, H733, H832A and H833 pressure relief valves with relief pressure settings up to 200 psig.** These units were manufactured from April 2013 to April 2015. Relief valves with setpoints over 200 psig are not included in this voluntary recall.

Please contact Emerson Process Management Regulator Technologies or your current Fisher LP distributor on or after August 17, 2015 to request a redesigned Fisher model H733 or H833 pressure relief valve. These replacement valves serve as replacements for all four of the recalled model valves and will be provided to you free of charge. For a list of current Fisher LP distributors in your area, go to [www.FisherRegulators.com](http://www.FisherRegulators.com) or you may call (888) 237-1751 for assistance in locating the distributor in your area.



Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of the notice to the vehicle lessee within ten days.

You may submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave., SE, Washington, D.C. 20590 or call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153) or go to <http://www.safercar.gov>, if you believe that Emerson Process Management Regulator Technologies, Inc. has failed or is unable to remedy your pressure relief valve without charge.

We regret any inconvenience this voluntary recall may cause you. If you have any questions regarding this recall, you may call Emerson Process Management Regulator Technologies, Inc. at (888) 237-1751.

Sincerely,

A handwritten signature in black ink, appearing to read "Andrew Lukensmeyer", with a long horizontal flourish extending to the right.

Andrew Lukensmeyer  
Product Safety Officer  
Emerson Process Management Regulator Technologies