



**NOTICE OF AUTHORIZATION TO APPLY THE UL MARK**

2008-12-22

Mr. Jerry Flock  
Rosemount Analytical Inc  
2400 Barranca Pky  
Irvine, CA 92606  
United States

Fax number: 949-474-7250

E-mail: jerry.flock@emersonprocess.com

Reference: File E207618 Project 07CA65455 P.O. Number MR JERRY, FLOCK

Product: USL/CNL- DUAL INPUT INTELLIGENT ANALYZER, MODELS 1056-01, 1056-02, 1056-03

Dear Mr. Flock,

Any information and documentation involving UL Mark services are provided on behalf of Underwriters Laboratories Inc. (UL) or any authorized licensee of UL.

UL's investigation of your product has been completed under the above project number and the subject product was determined to comply with the applicable requirements.

This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Listing Mark only at the factory under UL's Follow-Up Service Program to the subject product, which is constructed as described below:

Similar to the subject models, which were submitted to UL for this investigation. The UL Records covering the product will be in the Follow-Up Services Procedure, File E207618, Volume 2.

To provide the manufacturer with the intended authorization to use the UL Mark, the addressee must send a copy of this Notice and all attached material to each manufacturing location as currently authorized in File E207618, Volume 2.

This authorization is effective from the date of this Notice and only for products at the indicated manufacturing locations. Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent to the indicated manufacturing locations in the near future. Please note that Follow-Up Services Procedures are sent to the manufacturers only unless the Applicant specifically requests this document.

Products that bear the UL Mark shall be identical to those that were evaluated by UL and found to comply with UL's requirements. If changes in construction are discovered, appropriate action will be taken for products not in conformance with UL's requirements and continued use of the UL Mark may be withdrawn.

Sincerely,

Reviewed by:

Rudy Manzano  
Senior Project Engineer  
Department: 3013ESCL  
Tel: 408-754-6546  
Fax: 408-689-6546  
E-mail: rudy.manzano@us.ul.com

Jeff Eirich  
Staff Engineer  
Department: 3013ESCL  
E-mail: jeff.d.eirich@us.ul.com