Rosemount Analytical ADDENDUM


MODEL CAT100 INSTRUCTION MANUAL 748441

This addendum serves as an amendment to the Model CAT100 Instruction Manual 748441. The following information should be considered part of the manual, and supersedes any conflicting information in the body of the manual.

READ THIS INFORMATION AND NOTE THE CONFLICTS.

INCREASED SAFETY BOX WIRING DIAGRAM (DWG 659921, SHEET 2)

The wiring diagram (659921, sheet 2) provided in the rear of the instruction manual does not indicate the correct wire colors for the internal wiring of the Increased Safety Junction Box. The wiring diagram provided in this addendum shows the correct wiring colors for the internal wiring of the Increased Safety Junction Box.



2 of 2 Rosemount Analytical January 2001 748449-A