POWER ROSEMOUNT 5300

Power Plant Achieves Reliable Boiler Drum Level Control with Rosemount™ Guided Wave Radar

RESULTS

- Reduced maintenance with no calibration required
- Increased accuracy with more rapid drum level readings
- Elimination of unwarranted trips due to cold ambient conditions



APPLICATION

Boiler drum level control at a combined cycle power plant.

CUSTOMER

NA natural gas combined cycle gas plant located in USA with a capacity of over 900 MW

CHALLENGE

During the winter months, sub-freezing temperatures are common in this region which creates challenges for the company's drum level measurement instrumentation.

The primary level measurement on the boiler drums were differential pressure transmitters with impulse tubing (wet legs). During winter months frozen wet legs caused errors in the indicated drum levels resulting in unit trips. To alleviate the problem, the impulse tubes were insulated and heat traced but the impulse tubes continued to freeze.

SOLUTION

As a result, the gas site systems engineer decided to investigate alternative technologies to improve the reliability of the boiler drum level instrumentation. With support from Emerson™ experts, they installed Rosemount 5300 Guided Wave Radar with Dynamic Vapor Compensation (DVC) along with a Rosemount 9901 bypass chamber.

With process design conditions exceeding 2300 psi and 650° F, the Rosemount 5300 with DVC provided fully compensated level measurements, independent of pressure and temperature, resulting in accurate and reliable level readings during all start-up and shutdown conditions, regardless of the weather.

"Since converting to the Rosemount 5300 with Dynamic Vapor Compensation, unit reliability has significantly increased."

Manager of Gas and Turbine Engineering




Illustration showing how Dynamic Vapor Compensation works



The plant used a two out of three voting system with three redundant radar installations. Since installation, the Rosemount 5300 with Dynamic Vapor Compensation has proved to be very reliable. The radar levels cannot deviate from each other by more than 2.5" (6.35cm) without causing the boiler to trip. Since installation, they have all tracked reliably and within the manufacturer's specification.

Emerson technicians performed on-site startup of the radars and provided formal training for the site operators to ensure confidence in the new product.

"With the proven reliability of the Rosemount 5300 with DVC, we are working to implement them as a best practice for the combined cycle fleet"

Manager of Gas and Turbine Engineering

RESOURCES

Rosemount 5300 Guided Wave Radar

EmersonProcess.com/Rosemount/Guided-Wave-Radar/5300

Emerson Process Management Power Industry

EmersonProcess.com/Industries/Power

Standard Terms and Conditions of Sale can be found at www.Emerson.com/en-us/pages/Terms-of-Use.aspx

The Emerson logo is a trademark and service mark of Emerson Electric Co. Rosemount and the Rosemount logotype are trademarks of Emerson Process Management.

All other marks are the property of their respective owners. © 2016 Emerson Process Management. All rights reserved.

Europe Regional Office Emerson Process Management Europe GmbH

Neuhofstrasse 19a P.O. Box 1046. CH 6340 Baar, Switzerland

+41 (0) 41 768 6111

+41 (0) 41 768 6300

RFQ.RMD-RCC@EmersonProcess.com

Middle East & Africa Regional Office **Emerson Process Management**

Emerson FZE P.O. Box 17033 Jebel Ali Free Zone - South 2 Dubai, United Arab Emirates

+971 4 811 8100

+971 4 886 5465

RFO.RMDMEA@EmersonProcess.com

Asia Pacific Regional Office Emerson Process Management Asia Pacific Pte Ltd

1 Pandan Crescent Singapore 128461

Linkedin.com/company/Emerson-Process-Management

Youtube.com/user/RosemountMeasurement

Google.com/+RosemountMeasurement

Twitter.com/Rosemount_News

Facebook.com/Rosemount

+65 6777 8211

+65 6777 0947

Enquiries@AP.EmersonProcess.com

00830-2100-4530 Rev AA

Global Headquarters

Shakopee, MN 55379 USA

+1 952 949 7001

6021 Innovation Blvd

Emerson Process Management

+1 800 999 9307 or +1 952 906 8888

RFQ.RMD-RCC@EmersonProcess.com



ROSEMOUNT